



Resene Construction Systems  
PO Box 39108  
Harewood  
Christchurch  
8545

**IDENTIFICATION OF ASBESTOS IN A BULK SAMPLE**

Samples received on 24/11/2021 from Unknown. Sampled by Mark Flewelling on 18/11/2021

NOTES:

The results within this report only relate to the samples tested.

Sampling was conducted by yourselves (or agent). Results pertain to sample 'as received'.

This report may not be reproduced, except in full.

In-house Method: Based on Australian Standard: AS 4964-2004, Method for the identification of asbestos in bulk samples and HSG 248 The Analyst Guide for sampling, analysis and clearance procedures (2005).

**Asbestos types: Amosite or Brown asbestos, Crocidolite or Blue asbestos, Chrysotile or White asbestos, fibrous Anthophyllite, Actinolite, and Tremolite.**

DOA: Date of Analysis. Noted for each sample below the sample number.

Where present "A" denotes an amendment and this report supersedes the original report number.

\*Asbestos is a hazard. Provided it is incorporated into a stable matrix and no airborne dust is produced it presents minimal health risk. Any asbestos detected follows the definition of "asbestos" (even as a contaminant) in The Health and Safety at Work (Asbestos) Regulations 2016.

**Results**

Sample # & DOA	Sample Details	Asbestos Types Detected
52665 25/11/21	Ceramic firewool	No Asbestos Detected
*Comments	Fibreglass - Insulation. Due to the large size of the sample a representative portion was analysed.	

\*Analysts' interpretations and opinions expressed in this report are outside the terms of this Laboratory's Accreditation.

Authorised By:  
Chelsea Wright  
Key Technical Person

Reported By:  
Chelsea Wright  
Senior Analyst



All tests reported herein have been performed in accordance with the laboratory's scope of accreditation